
Assembly instruction

Kos 3so





You need









Components

Α



Ŀ



Nr	QTY	mm
Α	4	H: 160
В	16	M8x30
С	4	

C



D




ſ



Nr	QTY	mm
D	4	H: 150
С	4	

Mounting

Follow the instructions step by step



Mounting

Follow the instructions step by step

